Supervisor Controller Version 2.14F01 And Above Now Supports M400 Without A License

Supervisor versions 2.14F01 and above now support the Control Techniques™ M400 VFD as a non-licensed, native device.

Issue

Current M400 ADFs installed on Supervisor Controllers must be *uninstalled prior to upgrading to Supervisor version 2.14F01 and above* to avoid conflicts with the new, non-licensed M400 version.

Affected Versions

- Supervisor versions 2.14F01 and Above
- M400 VFD ADF# 531-0111

Who is Affected

- Customers currently using licensed versions of the M400, ADF# 531-0111

Removal and Upgrade Procedure

1. Before upgrading to version 2.14F01, locate the M400 ADF on your Supervisor and remove.
2. From the Home page, click the gear icon ⚙ .
3. Select **Configure System** > **File Management & Licensing**.
4. From this screen, you can select the License Key and click **Delete** to remove the license from the system.
5. Proceed to upgrade your Supervisor to version 2.14F01.

Scan the QR code to access the Site Supervisor web page:

Visit our website at **copeland.com/en-us/products/controls-monitoring-systems** for the latest technical documentation and updates.
For Technical Support call **833-409-7505** or email **ColdChain.TechnicalServices@Copeland.com**

COPELAND