



NOTIFICATION: Discontinuation of all SK/HSK VFDs
EFFECTIVE DATE: 9/14/2017

EOL REASON: Discontinued by the manufacturer

LAST PURCHASE DATE: September 30, 2017
LAST SHIP DATE: September 30, 2017
CONTACT: Emerson Retail Solutions Sales Dept.
ACTION REQUIRED: Discontinuation of the SK/HSK VFDs and the recommended replacement products are the M400 Series VFDs.

Table 1 – End-of-Life (EOL) Product Description and Replacement Product Information

Part Numbers of EOL Products		Product Description	Replacement Product Part Numbers	Replacement Product Description
221-8050	221-8051	All SK/HSK VFDs	802-0076	M400 Series VFDs
221-8060	221-8065		802-0077	
319-0021	319-0044		802-0078	
319-0055	319-0058		802-0079	
319-0059	319-0060		802-2000	
319-0061	319-0064		802-2002	
802-0001	802-0002		802-2003	
802-0003	802-0004		802-2004	
802-0005	802-0006		802-2005	
802-0007	802-0008		802-2006	
802-0009	802-0010		802-2007	
802-0011	802-0012		802-2008	
802-0013	802-0014		802-2009	
802-0015	802-0016		802-2010	
802-0017	802-0018		802-2011	
802-0019	802-0029		802-2012	
802-0030	802-0031		802-2013	
802-0032	802-0033		802-2014	
802-0034	802-0035		802-2015	
802-0036	802-0037		802-2016	
802-0038	802-0039		802-2017	
802-0040	802-0041		802-2018	
802-0042	802-0043		802-2019	
802-0044	802-0045		802-2020	
802-0046	802-0047		802-2021	
802-0051	802-0060		802-2022	
802-0061	802-0062		802-2023	
802-0063	802-0064		802-2024	
802-0065	802-0066		802-2025	
802-0067	802-0068		802-2026	
802-0069	802-0070		802-2027	
802-0071	802-0072			
802-0073	802-0074			
802-1000	802-2001			

The SK/HSK VFDs have been discontinued. The recommended replacement products are the M400 Series VFDs. Please contact your Emerson Retail Solutions Sales Representative for more information.