



**NOTIFICATION:** Discontinuation of the **Control Techniques Commander SK/HSK VFD drives**  
**EFFECTIVE DATE:** **3/23/2017**  
**EOL REASON:** Discontinued  
**LAST PURCHASE DATE:** **3/31/2017**  
**LAST SHIP DATE:** **3/31/2017**  
**CONTACT:** Emerson Retail Solutions Sales Dept.  
**ACTION REQUIRED:** **Recommended Substitution – Unidrive M400 products**

### **Product Description and Replacement Product Information**

The Commander SK/HSK product line will be discontinued effective March 31st, 2017.

If you are planning to purchase SK/HSK drives 1-100 HP, or replace SK/HSK drives, the recommended replacement drive is Control Techniques M400.

If you require assistance with migration to the M400, please contact your local Emerson Sales Representative for more information.