

E2 2.62F01 Now Available

A new version of the E2 controller firmware, version 2.62F01, has been released and is available for customer upgrade. The package file used for upgrade may be downloaded from the Retail Solutions website:

<http://www.emersonretailsolutions.com/supermarkets/firmware.asp>

Instructions on how to use UltraSite32 to deploy the upgrade package may be found in the Retail Solutions library:

<http://www.emersonretailsolutions.com/library/index.asp>

2.62F01 adds the following fixes and enhancements:



- Fixes SRAM heap memory leak that may cause some E2s using ProAct Monitoring to run out of memory.
- Adds support for Control Link RSC version 4.10.
- Enhancements to licensed Web Services feature, including improved graphical look & feel and pop-up graph views for point data.

Who Should Update

Retail Solutions recommends as a policy all customers upgrade their E2 controllers to the latest firmware version to take advantage of the latest fixes and enhancements. Customers are strongly advised to upgrade to 2.62F01 if any of the following conditions apply:

- **Sites being monitored using Retail Solutions Monitoring software.**
- **Sites with E2s that will network with Control Link RSC version 4.10.**
- **Sites with E2s using Web Services.**

Documentation Updates and New Documentation

No documentation changes were made to support new features in E2 2.62F01. Refer to the E2 on-line help for assistance in setting up new E2 features.

The E2 manual and other user documentation may be viewed and downloaded from the Retail Solutions library:
<http://www.emersonretailsolutions.com/library/index.asp>