# Site Supervisor

## Update Advisory Site Supervisor 2.08F01

A new general release version of the Site Supervisor Controller firmware, version 2.08F01, has been released and is available for customer upgrade. For more information, visit the Site Supervisor page on the Copeland website:

https://www.copeland.com/en-us/products/controls-monitoring-systems/facility-controls-electronics/facility-and-system-controls/supervisory-controls-platform



## Site Supervisor 2.08F01 Adds the Following Features and Enhancements:

Table 1: Site Supervisor 2.08F01 Fix and Feature Matrix

Fix and Feature Descriptions	Supported in Site Supervisor 2.08F01
Flex Combiner Pointer & I/O Name Support	✓
Password Reset Enhancements	✓
BACnet Support Added	✓
User Session Timeout Enhancements	✓
Site Aggregation at Sites with Mixed Controller Types	✓
Alarm Page Enhancements	✓
General System Property Page Menu Enhancements	✓
Conditional Visibility Enhancements	✓
Defrost Icon Matches Defrost Color in Site Manager	✓
RLDS Support for Additional Refrigerants	✓
Copeland Programmable Touchscreen Thermostat Native Application Support	✓
Chiller Application Enhancements	✓
License Key Entry Enhancements	✓



### Who Should Update

Copeland recommends that all customers upgrade their Site Supervisor Controllers and PCs running Site Manager to the latest version to take advantage of the latest fixes and enhancements listed above.

All customers who meet one or more of the requirements below are advised to upgrade to Site Supervisor 2.08F01:

Customers using any of the features listed in Table 1:

#### Site Manager and Connect+ Minimum Version Compatibility

#### Table 2: Site Manager and Connect+ Compatibility Matrix

Site Supervisor 2.08F01		
Site Manager Minimum Version	Connect+ Minimum Version	
18.2.1	1.3.1	

# Site Manager and Connect+ Updates Required

Site Supervisor requires Site Manager 18.2.1 or greater, or Connect+ 1.3.1 or greater. It is recommended the latest version of Site Manager and Connect+ be installed for best practices. If communication with Site Manager or Connect+ is required, upgrade Site Manager or Connect+ to the latest version first, then update the Site Supervisor Controllers. Contact Copeland for more information about upgrading.

## For Technical Support:

- +1770-425-2724
- ColdChain.TechnicalServices@Copeland.com

Scan the QR code to access the Supervisory Control Platform web page:



Visit our website at copeland.com/en-us/products/controls-monitoring-systems for the latest technical documentation and updates. For Technical Support call 833-409-7505 or email ColdChain.TechnicalServices@Copeland.com

