Gas Leak DetectionDISCONTINUATION of MRLDS-CO2

EOL#1906 Rev 0 28-AUG-2019

NOTIFICATION: Discontinuation of the MRLDS-CO2, part number 809-1020

EFFECTIVE DATE: 28-AUG-2019

EOL REASON: Discontinuing manufacturing of the product

LAST PURCHASE DATE:30-SEP-2019LAST SHIP DATE:31-OCT-2019

CONTACT: Emerson Sales Dept.

ACTION REQUIRED: Discontinuation of the MRLDS-CO2, part number 809-1020 replaced by MRLDS-450, part number

809-1040, effective August 28, 2019.

Table 1 – End-of-Life (EOL) Product Description and Replacement Product Information

Part Number of EOL Product	Product Description	Replacement Product Part Number	Replacement Product Description
809-1020	MRLDS-C02, 0-5,000ppm, IP66	809-1040	MRLDS-450, CO2, 0-5,000ppm, IP66
		809-1041	MRLDS-450, CO2, 0-10,000ppm, IP66

Notable differences of the replacement leak detector:

• The new MRLDS-450 has (3) relay outputs, an analog output and a Modbus output, whereas the MRLDS-CO2 only had a relay output and analog output.

Emerson 1065 Big Shanty Road NW. Suite 100, Kennesaw, GA 30144 770-425-2724 • <u>www.emerson.com</u>

The contents of this publication are presented for informational purposes only and they are not to be construed as warranties or guarantees, express or implied, regarding the products or services described herein or their use or applicability. Emerson Climate Technologies Retail Solutions, Inc. and/or its affiliates (collectively "Emerson"), reserves the right to modify the designs or specifications of such products at any time without notice. Emerson does not assume responsibility for the selection, use or maintenance of any product. Responsibility for proper selection, use and maintenance of any product remains solely with the purchaser and end-user.

Emerson is a trademark of Emerson Electric Co. © 2019 Emerson Climate Technologies Retail Solutions, Inc. All rights reserved.